

CVEs Addressed	Product	Software/Firmware	Affected Versions	Remediated Versions	Release Date (MM/DD/YYYY)	Link
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Alienware 16 Area-51 AA16250	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/10/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-	Alienware 16 Area-51 AA16250	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Controller Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	11/10/2025	Go to the Drivers & Downloads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware 18 Area-51 AA18250	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/10/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware 18 Area-51 AA18250	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	11/10/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware Area 51m R2	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	10/21/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware Area 51m R2	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	10/21/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware Area- 51 AAT2250	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/18/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware Area- 51 AAT2250	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	11/18/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware Aurora ACT1250	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/18/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware Aurora ACT1250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/18/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware Aurora R13	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	09/08/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware Aurora R13	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	09/08/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware Aurora R13	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	09/08/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware Aurora R15	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	09/08/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware Aurora R15	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	09/08/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware Aurora R15	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	09/08/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware m15 R4	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	10/21/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware m15 R4	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	10/21/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware m15 R6	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/10/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware m15 R6	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	11/10/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware m15 R7	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/10/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware m15 R7	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/10/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware m15 R7	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	11/10/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware m15 Ryzen Edition R5	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/10/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware m15 Ryzen Edition R5	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Controller Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	11/10/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware m16 R1	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/12/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware m16 R1	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	11/12/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware m16 R2	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/12/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware m16 R2	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/12/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware m16 R2	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	11/12/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware m17 R3	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	10/21/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware m17 R3	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	10/21/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware m17 R4	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	10/21/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware m17 R4	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	10/21/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware m18 R1	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/12/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware m18 R1	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	11/12/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware M18 R2	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/12/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware M18 R2	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	11/12/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware x14	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/12/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware x14	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/12/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware x14	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Controller Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	11/12/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware x14 R2	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/09/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware x14 R2	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/09/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware x14 R2	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Controller Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	11/09/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware x15 R1	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/10/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware x15 R1	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Controller Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	11/10/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware x15 R2	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/12/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware x15 R2	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Controller Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	11/12/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware x16 R1	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/07/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware x16 R1	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Controller Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	11/07/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware X16 R2	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	10/15/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware X16 R2	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Controller Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	10/17/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware x17 R1	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/10/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware x17 R1	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	11/10/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Alienware x17 R2	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/12/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Alienware x17 R2	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	11/12/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	AURORA R16	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/18/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	AURORA R16	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	11/18/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	ChengMing 3900	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/13/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	ChengMing 3900	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/13/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	ChengMing 3990	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/13/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	ChengMing 3990	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/13/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	ChengMing 3991	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/13/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	ChengMing 3991	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/13/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Dell 14 Plus 2- in-1 DB04250	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/06/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Dell 14 Plus 2- in-1 DB04250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/06/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Dell 14 Plus DB14250	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/06/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Dell 14 Plus DB14250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/06/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Dell 14 Premium DA14250	Intel BE201/BE200/AX211 Wi- Fi Controller Driver and Killer Intelligence Center Application	Version s prior to 36.25.3 253	Version 36.25.32 53 or later	09/08/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Dell 14 Premium DA14250	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	09/08/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Dell 16 Plus 2- in-1 DB06250	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/06/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Dell 16 Plus 2- in-1 DB06250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/06/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Dell 16 Plus DB16250	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/06/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Dell 16 Plus DB16250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/06/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Dell 16 Premium DA16250	Intel BE201/BE200/AX211 Wi- Fi Controller Driver and Killer Intelligence Center Application	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	10/09/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Dell 16 Premium DA16250	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	10/09/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Dell 24 All-in-One EC24250	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/19/2025	Go to the Drivers & Downloads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Dell 24 All-in-One EC24250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/19/2025	Go to the Drivers & Downloads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	DELL 27 All-in-One EC27250	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/19/2025	Go to the Drivers & Downloads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	DELL 27 All-in-One EC27250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/19/2025	Go to the Drivers & Downloads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Dell G15 5510	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/10/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Dell G15 5510	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/10/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Dell G15 5510	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	11/10/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Dell G15 5511	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/10/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Dell G15 5511	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/10/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Dell G15 5511	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	11/10/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Dell G15 5515	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	10/23/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Dell G15 5515	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Controller Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	10/23/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Dell G15 5520	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/09/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Dell G15 5520	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/09/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Dell G15 5520	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	11/09/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Dell G15 5530	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	10/15/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Dell G15 5530	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	10/15/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Dell G16 7620	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/09/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Dell G16 7620	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/09/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Dell G16 7620	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	11/09/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Dell G16 7630	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	10/15/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Dell G16 7630	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	10/15/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Dell G16 7630	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	10/15/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Dell G5 5000	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	09/08/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Dell G5 5000	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	09/08/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Dell G5 5090	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	09/08/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Dell G5 5090	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3 250	Version 36.25.32 50 or later	09/08/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025-	Dell Precision 3430 Tower	Intel 9560/9260 Bluetooth UWD Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/18/2025	Go to the Drivers & Downlo ads site for updates

35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Dell Precision 3430 Tower	Intel 9560/9260 Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/18/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 20062, CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025-	Dell Precision 3431 Tower	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/06/2025	Go to the Drivers & Downlo ads site for updates

35963, CVE- 2025- 35967, CVE- 2025- 35971						
CVE- 2025- 20062, CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Dell Precision 3431 Tower	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/06/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025-	Dell Precision 3630 Tower	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	10/08/2025	Go to the Drivers & Downlo ads site for updates

33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971						
CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Dell Precision 3630 Tower	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	10/08/2025	Go to the Drivers & Downlo ads site for updates
CVE- 2025- 20062, CVE- 2025- 24512, CVE- 2025-	Dell Pro 13 Plus PB13250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/16/2025	Go to the Drivers & Downlo ads site for updates

30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971						
CVE- 2025- 20062, CVE- 2025- 24512, CVE- 2025- 30255, CVE- 2025- 33029, CVE- 2025- 35963, CVE- 2025- 35967, CVE- 2025- 35971	Dell Pro 13 Plus PB13250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/16/2025	Go to the Drivers & Downlo ads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro 13 Plus PB13250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Dell Pro 13 Plus PB13250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro 13 Premium PA13250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/17/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	Dell Pro 13 Premium PA13250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/17/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro 14 PC14250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	Dell Pro 14 PC14250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	Dell Pro 14 Plus PB14250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/20/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro 14 Plus PB14250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	10/20/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	Dell Pro 14 Plus PB14250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	10/20/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro 14 Plus PB14250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/20/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	Dell Pro 14 Premium PA14250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/17/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro 14 Premium PA14250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/17/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro 16 PC16250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Dell Pro 16 PC16250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro 16 Plus PB16250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	Dell Pro 16 Plus PB16250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro 16 Plus PB16250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	Dell Pro 16 Plus PB16250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	Dell Pro 24 All-in-One Plus/Dell Pro 24 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/18/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro 24 All-in-One Plus/Dell Pro 24 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/18/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	Dell Pro Laptop PC14250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro Laptop PC14250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	Dell Pro Laptop PC16250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro Laptop PC16250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro Max 14 MC14250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/18/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Dell Pro Max 14 MC14250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/18/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro Max 14 Premium MA14250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/20/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	Dell Pro Max 14 Premium MA14250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/20/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro Max 16 MC16250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/18/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	Dell Pro Max 16 MC16250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0.4 or later	11/18/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	Dell Pro Max 16 Plus MB16250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/13/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro Max 16 Plus MB16250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	10/13/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	Dell Pro Max 16 Premium MA16250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	10/20/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro Max 16 Premium MA16250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/20/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	Dell Pro Max 18 Plus MB18250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/13/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro Max 18 Plus MB18250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/13/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro Max Micro FCM2250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/18/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Dell Pro Max Micro FCM2250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/18/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro Max Slim FCS1250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	Dell Pro Max Slim FCS1250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro Max Tower T2 FCT2250	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/14/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Dell Pro Max Tower T2 FCT2250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/14/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro Micro/Micro Plus QCM1250/QBM1250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/17/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	Dell Pro Micro/Micro Plus	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0.4 or later	10/17/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	QCM1250/QBM1250		23.160.0.4			Downlo ads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro Micro/Micro Plus QCM1250/QBM1250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/17/2025	Go to the Drivers & Downlo ads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro Rugged 13 RA13250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Dell Pro Rugged 13 RA13250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro Rugged 14 RB14250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	Dell Pro Rugged 14 RB14250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro Slim Plus QBS1250/Dell Pro Slim QCS1250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	Dell Pro Slim Plus QBS1250/Dell	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Pro Slim QCS1250		23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	Dell Pro Slim Plus QBS1250/Dell Pro Slim QCS1250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro Slim Plus QBS1250/Dell Pro Slim QCS1250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	Dell Pro Tower Plus QBT1250/Dell Pro Tower QCT1250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/16/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Pro Tower Plus QBT1250/Dell Pro Tower QCT1250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Dell Pro Tower Plus QBT1250/Dell Pro Tower QCT1250	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/16/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Slim ECS1250	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/15/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Dell Slim ECS1250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/15/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Tower ECT1250	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/15/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Dell Tower ECT1250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/15/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Dell Tower Plus EBT2250	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/18/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Dell Tower Plus EBT2250	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/18/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 13 5310	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/12/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 13 5310	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/12/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 13 5320	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 13 5320	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 13 5330	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/13/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 13 5330	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/13/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 13 5330	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/13/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 14 5410 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/20/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 14 5410 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/20/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 14 5420	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 14 5420	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 14 5430	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 14 5430	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 14 7420 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 14 7420 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 14 7430 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 14 7430 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 14 7440 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/11/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 14 7440 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/11/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 14 Plus 7420	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 14 Plus 7420	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 14 Plus 7430	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 14 Plus 7430	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 14 Plus 7440	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 14 Plus 7440	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 14 Plus 7440	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 15 3510	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/10/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 15 3510	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/10/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 15 3511	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/10/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 15 3511	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/10/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 15 3520	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/12/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 15 3520	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/12/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 15 3521	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/10/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 15 3521	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/10/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 15 7510	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/10/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 15 7510	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/10/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 16 5620	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 16 5620	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 16 5630	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 16 5630	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 16 7610	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/10/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 16 7610	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/10/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 16 7620 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 16 7620 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 16 7630 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 16 7630 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 16 7640 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 16 7640 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 16 Plus 7620	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 16 Plus 7620	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 16 Plus 7630	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 16 Plus 7630	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 16 Plus 7640	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 16 Plus 7640	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 16 Plus 7640	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 24 5420 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/19/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 24 5420 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/19/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 24 5430 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/17/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 24 5430 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/17/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 27 7720 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/19/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 27720 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/19/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 27730 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/17/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 27 7730 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/17/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 3020 Desktop	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/13/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 3020 Desktop	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/13/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 3020 Small Desktop	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/15/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 3020 Small Desktop	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/15/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 3030	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/15/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 3030	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/15/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 3030S	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/15/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 3030S	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/15/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 3501	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/12/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 3501	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/12/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 3501	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/12/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 3501	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/12/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 3502	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/08/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 3502	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/08/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 3880	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/13/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 3880	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/13/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 3891	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/13/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 3891	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/13/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 3910	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/13/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 3910	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/13/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 5400/5401	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/16/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 5400/5401	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 5401 AIO	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/16/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 5401 AIO	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 5410	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/18/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 5410	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/18/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 5410 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/19/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 5410 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/19/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 5510	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/18/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 5510	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/18/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 7415 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	12/09/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 7415 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	12/09/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 7700 All-In-One	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/16/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 7700 All-In-One	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Inspiron 7710 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/19/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Inspiron 7710 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/19/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	Latitude 3120	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3120	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3140	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Latitude 3140	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3301	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/20/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Latitude 3301	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/20/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3310	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	Latitude 3310	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3310 2-In-1	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	Latitude 3310 2-In-1	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3320	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/12/2025	Go to the Drivers & Downlo ads site for updates

CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3320	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/12/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3330	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/12/2025	Go to the Drivers & Downloads site for updates

CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3330	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/12/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3340	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/12/2025	Go to the Drivers & Downloads site for updates

CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3340	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/12/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3340	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/12/2025	Go to the Drivers & Downloads site for updates

CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3340	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/12/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3400	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/18/2025	Go to the Drivers & Downloads site for updates

CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3400	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/18/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3410	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/11/2025	Go to the Drivers & Downloads site for updates

CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3410	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/11/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3420	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/11/2025	Go to the Drivers & Downloads site for updates

CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3420	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/11/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3430	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/12/2025	Go to the Drivers & Downloads site for updates

CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3430	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/12/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3440	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/12/2025	Go to the Drivers & Downloads site for updates

CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3440	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/12/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3450	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/12/2025	Go to the Drivers & Downloads site for updates

CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3450	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/12/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3500	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/18/2025	Go to the Drivers & Downloads site for updates

CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3500	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/18/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3510	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/11/2025	Go to the Drivers & Downloads site for updates

CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3510	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/11/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3520	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/11/2025	Go to the Drivers & Downloads site for updates

CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3520	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/11/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3530	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/12/2025	Go to the Drivers & Downloads site for updates

CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3530	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/12/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3540	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/12/2025	Go to the Drivers & Downloads site for updates

CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3540	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/12/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3550	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/12/2025	Go to the Drivers & Downloads site for updates

CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 3550	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/12/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	Latitude 5300	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/05/2025	Go to the Drivers & Downloads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5300	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/05/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	Latitude 5300 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/05/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5300 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/05/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	Latitude 5310	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/05/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5310	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/05/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5310 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/05/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Latitude 5310 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/05/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5320	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/18/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	Latitude 5320	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/18/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5330	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/18/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	Latitude 5330	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0. 4 or later	11/18/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	Latitude 5340	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/16/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5340	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	Latitude 5350	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/19/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5350	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/19/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	Latitude 5400	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/05/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5400	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/05/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5401	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/04/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Latitude 5401	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/04/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5410	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/05/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	Latitude 5410	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/05/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5411	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/04/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	Latitude 5411	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0. 4 or later	11/04/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	Latitude 5420	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/18/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5420	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/18/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	Latitude 5421	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5421	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	Latitude 5430	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/18/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5430	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/18/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5430 Rugged Laptop	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Latitude 5430 Rugged Laptop	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5431	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	Latitude 5431	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5440	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	Latitude 5440	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0. 4 or later	11/16/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	Latitude 5450	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/17/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5450	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/17/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Latitude 5491	Intel 9560/9260 Bluetooth UWD Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5491	Intel 9560/9260 Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	Latitude 5500	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/05/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5500	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/05/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	Latitude 5501	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/04/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5501	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/04/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5510	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/05/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Latitude 5510	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/05/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5511	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/04/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	Latitude 5511	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/04/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5520	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/18/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	Latitude 5520	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0. 4 or later	11/18/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	Latitude 5521	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5521	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	Latitude 5530	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/18/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5530	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/18/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	Latitude 5531	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5531	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5540	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Latitude 5540	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5550	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/19/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	Latitude 5550	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/19/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 5591	Intel 9560/9260 Bluetooth UWD Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Latitude 5591	Intel 9560/9260 Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/06/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7030 Rugged Extreme	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/20/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	Latitude 7030 Rugged Extreme	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0.4 or later	10/20/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	Latitude 7200 2-In-1	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/04/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7200 2-In-1	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/04/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	Latitude 7210 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/04/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7210 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/04/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	Latitude 7220 Rugged Extreme	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7220 Rugged Extreme	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7230 Rugged Extreme	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/17/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Latitude 7230 Rugged Extreme	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/17/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7300	Intel AX200/AX201/9260/9560 Wi-Fi UWD Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Latitude 7300	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7310	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/04/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	Latitude 7310	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/04/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7320	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	Latitude 7320	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0. 4 or later	11/16/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	Latitude 7320 Detachable	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/18/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7320 Detachable	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/18/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	Latitude 7330	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7330	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	Latitude 7330 Rugged Laptop	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7330 Rugged Laptop	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7340	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Latitude 7340	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7350	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	Latitude 7350	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7350 Detachable	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/17/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	Latitude 7350 Detachable	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0.4 or later	10/17/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7400	Intel AX200/AX201/9260/9560 Wi-Fi UWD Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downlo ads site for updates

CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7400	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	Latitude 7400 2-In-1	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/04/2025	Go to the Drivers & Downloads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7400 2-In-1	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/04/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	Latitude 7410	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/04/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7410	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/04/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	Latitude 7420	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7420	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7430	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Latitude 7430	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7440	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	Latitude 7440	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7450	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	10/17/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	Latitude 7450	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0. 4 or later	10/17/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	Latitude 7520	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7520	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	Latitude 7530	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7530	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	Latitude 7640	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7640	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 7650	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/17/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Latitude 7650	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/17/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 9330	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	Latitude 9330	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 9410	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/04/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	Latitude 9410	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0. 4 or later	11/04/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	Latitude 9420	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/18/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 9420	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/18/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	Latitude 9430	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/18/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 9430	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/18/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	Latitude 9440 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/18/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 9440 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/18/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 9450	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/17/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Latitude 9450	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/17/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 9510 2in1	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	Latitude 9510 2in1	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude 9520	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	Latitude 9520	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	Latitude Rugged 7220EX	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Latitude Rugged 7220EX	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	OptiPlex 3000 Micro / OptiPlex 3000 Small Form Factor / OptiPlex 3000 Tower	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/19/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 3000 Micro / OptiPlex 3000 Small Form Factor / OptiPlex 3000 Tower	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/19/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	OptiPlex 3070	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/27/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 3070	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/27/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 3080	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	OptiPlex 3080	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 3090	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/21/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	OptiPlex 3090	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/21/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 3090 Ultra	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	10/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	OptiPlex 3090 Ultra	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0. 4 or later	10/16/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	OptiPlex 3280 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/20/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 3280 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/20/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	OptiPlex 5000 Micro / OptiPlex 5000 Small Form Factor / OptiPlex 5000 Tower	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/19/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 5000 Micro / OptiPlex 5000 Small Form Factor / OptiPlex 5000 Tower	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/19/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	OptiPlex 5070	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/27/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 5070	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/27/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 5080	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	OptiPlex 5080	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 5090 Micro / OptiPlex 5090 Small Form Factor / OptiPlex 5090 Tower	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	OptiPlex 5090 Micro / OptiPlex 5090 Small Form Factor / OptiPlex 5090 Tower	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 5270 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/04/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	OptiPlex 5270 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0.4 or later	11/04/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	OptiPlex 5400 All-In-One	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/17/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 5400 All-In-One	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/17/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	OptiPlex 5480 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/04/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 5480 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/04/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	OptiPlex 5490 AIO	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/30/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 5490 AIO	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/30/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 7000 Micro / OptiPlex 7000 Small Form Factor / OptiPlex 7000 Tower / OptiPlex 7000 XE Micro	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/19/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	OptiPlex 7000 Micro / OptiPlex 7000 Small Form Factor / OptiPlex 7000 Tower / OptiPlex 7000 XE Micro	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/19/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 7070	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	OptiPlex 7070	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 7070 UFF	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/18/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	OptiPlex 7070 UFF	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0.4 or later	11/18/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	Optiplex 7071	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Optiplex 7071	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	OptiPlex 7080	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/17/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 7080	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/17/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	OptiPlex 7090 Tower	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 7090 Tower	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 7090 Ultra	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	OptiPlex 7090 Ultra	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/16/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 7400 All-In-One	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/17/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	OptiPlex 7400 All-In-One	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/17/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 7470 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/18/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	OptiPlex 7470 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0.4 or later	11/18/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	OptiPlex 7480 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/04/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 7480 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/04/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	OptiPlex 7490 AIO	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	10/30/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 7490 AIO	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/30/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	OptiPlex 7770 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/18/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 7770 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/18/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex 7780 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/04/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	OptiPlex 7780 All-in-One	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/04/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex AIO 7420	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	OptiPlex AIO 7420	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex All-in-One 7410	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	10/20/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	OptiPlex All-in-One 7410	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0. 4 or later	10/20/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	OptiPlex Micro 7010 / OptiPlex Micro Plus 7010	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/16/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex Micro 7010 / OptiPlex Micro Plus 7010	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	OptiPlex Micro 7020	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/13/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex Micro 7020	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/13/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	OptiPlex SFF 7020	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/19/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex SFF 7020	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/19/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex Small Form Factor 7010 / OptiPlex Small Form Factor Plus 7010	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/17/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	OptiPlex Small Form Factor 7010 / OptiPlex Small Form Factor Plus 7010	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/17/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex Tower 7010 / OptiPlex Tower Plus 7010	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/19/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	OptiPlex Tower 7010 / OptiPlex Tower Plus 7010	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/19/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex Tower 7020	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/19/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	OptiPlex Tower 7020	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0.4 or later	11/19/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex XE3	Intel 9560/9260 Bluetooth UWD Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/19/2025	Go to the Drivers & Downlo ads site for updates

CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex XE3	Intel 9560/9260 Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/19/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	OptiPlex XE4 SFF	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/19/2025	Go to the Drivers & Downloads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex XE4 SFF	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/19/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	OptiPlex XE4 Tower	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/19/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	OptiPlex XE4 Tower	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/19/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	Precision 3240 CFF	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/22/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3240 CFF	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/22/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3260 XE Compact / Precision 3260 Compact	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Precision 3260 XE Compact / Precision 3260 Compact	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3280 CFF	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/17/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	Precision 3280 CFF	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/17/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3440	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	Precision 3440	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0. 4 or later	11/06/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	Precision 3450	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3450	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	Precision 3460 XE Small Form Factor / Precision 3460 Small Form Factor	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3460 XE Small Form Factor / Precision 3460 Small Form Factor	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	Precision 3470	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3470	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3480	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Precision 3480	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3490	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/17/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	Precision 3490	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/17/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3530	Intel 9560/9260 Bluetooth UWD Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Precision 3530	Intel 9560/9260 Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/06/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3540	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/05/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	Precision 3540	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0.4 or later	11/05/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	Precision 3541	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/04/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3541	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/04/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	Precision 3550	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/05/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3550	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/05/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	Precision 3551	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/04/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3551	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/04/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3560	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/18/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Precision 3560	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/18/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3561	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	Precision 3561	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3570	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/18/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	Precision 3570	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0. 4 or later	11/18/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	Precision 3571	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3571	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	Precision 3580	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3580	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	Precision 3581	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3581	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3590	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/19/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Precision 3590	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/19/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3591	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/19/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	Precision 3591	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/19/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3640	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/08/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Precision 3640	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/08/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3650 MT	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Precision 3650 MT	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/16/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3660	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/13/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Precision 3660	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/13/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 3680 Tower	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/13/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Precision 3680 Tower	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/13/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 5470	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	Precision 5470	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	Precision 5480	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 5480	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	Precision 5490	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	10/17/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 5490	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/17/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Precision 5540	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/22/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 5540	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/22/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Precision 5550	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/22/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 5550	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/22/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Precision 5560	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/11/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 5560	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/11/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Precision 5570	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/11/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 5570	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/11/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	Precision 5680	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 5680	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 5690	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/21/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Precision 5690	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/21/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 5750	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/20/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Precision 5750	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/20/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 5760	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/11/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Precision 5760	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/11/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 5770	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/11/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Precision 5770	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/11/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 7530	Intel 9560/9260 Bluetooth UWD Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/04/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Precision 7530	Intel 9560/9260 Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/04/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 7540	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	Precision 7540	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 7550	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/05/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	Precision 7550	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0. 4 or later	11/05/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	Precision 7560	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 7560	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	Precision 7670	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 7670	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-	Precision 7680	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site

2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 7680	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates

CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 7730	Intel 9560/9260 Bluetooth UWD Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/04/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 7730	Intel 9560/9260 Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/04/2025	Go to the Drivers & Downloads site for updates

CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 7740	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160. 0.9	Version 23.160.0. 9 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-	Precision 7740	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160. 0.4	Version 23.160.0. 4 or later	11/06/2025	Go to the Drivers & Downloads site for updates

2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 7750	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/05/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-	Precision 7750	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/05/2025	Go to the Drivers & Downloads site for updates

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 7760	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-	Precision 7760	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers &

2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971			23.160.0.4			Downlo ads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-	Precision 7770	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downlo ads site for updates

2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 7770	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-	Precision 7780	Intel BE2xx/AX4xx/AX2xx/9xxx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/16/2025	Go to the Drivers & Downloads site for updates

2025-35963, CVE-2025-35967, CVE-2025-35971						
CVE-2025-20062, CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Precision 7780	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/16/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Vostro 14 3420	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/12/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Vostro 14 3420	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/12/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Vostro 14 5410	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/18/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Vostro 14 5410	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/18/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Vostro 15 3510	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/10/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Vostro 15 3510	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/10/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Vostro 15 3520	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/12/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Vostro 15 3520	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/12/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Vostro 15 5510	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/18/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Vostro 15 5510	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/18/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Vostro 15 7510	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/10/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Vostro 15 7510	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/10/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Vostro 16 5630	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Vostro 16 5630	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Vostro 3020 Small Desktop	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/15/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Vostro 3020 Small Desktop	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/15/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Vostro 3020 Tower Desktop	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/13/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Vostro 3020 Tower Desktop	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/13/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Vostro 3030	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/15/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Vostro 3030	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/15/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Vostro 3030S	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/15/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Vostro 3030S	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/15/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Vostro 3400	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/12/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Vostro 3400	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/12/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Vostro 3401	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/12/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Vostro 3401	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/12/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Vostro 3500	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/12/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Vostro 3500	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/12/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Vostro 3501	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/12/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Vostro 3501	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/12/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Vostro 3681	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/17/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Vostro 3681	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/17/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Vostro 3710	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/15/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Vostro 3710	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/15/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Vostro 3881	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/13/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Vostro 3881	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/13/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Vostro 3888	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/13/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Vostro 3888	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/13/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Vostro 3910	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/13/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Vostro 3910	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/13/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Vostro 5320	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Vostro 5320	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Vostro 5620	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Vostro 5620	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	Vostro 7620	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/06/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	Vostro 7620	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/06/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	XPS 13 9305	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/11/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	XPS 13 9305	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Controller Driver	Version s prior to 36.25.3250	Version 36.25.3250 or later	11/11/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	XPS 13 2in1 9310	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/22/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	XPS 13 2in1 9310	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/22/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	XPS 13 2in1 9310	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Controller Driver	Version s prior to 36.25.3250	Version 36.25.3250 or later	10/22/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	XPS 13 9310	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/11/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	XPS 13 9310	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	11/11/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	XPS 13 9310	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Controller Driver	Version s prior to 36.25.3250	Version 36.25.3250 or later	11/11/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	XPS 13 9315	Intel BE201/BE200/AX211 Wi-Fi Controller Driver and Killer Intelligence Center Application	Version s prior to 36.25.3250	Version 36.25.3250 or later	11/10/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	XPS 13 9315	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/10/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	XPS 13 9340	Intel BE201/BE200/AX211 Wi-Fi Controller Driver and Killer Intelligence Center Application	Version s prior to 36.25.3250	Version 36.25.3250 or later	10/14/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	XPS 13 9340	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/14/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	XPS 13 9350	Intel BE201/BE200/AX211 Wi-Fi Controller Driver and Killer Intelligence Center Application	Version s prior to 36.25.3250	Version 36.25.3250 or later	10/14/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	XPS 13 9350	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/14/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	XPS 13 Plus 9320	Intel BE201/BE200/AX211 Wi-Fi Controller Driver and Killer Intelligence Center Application	Version s prior to 36.25.3250	Version 36.25.3250 or later	11/10/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	XPS 13 Plus 9320	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/10/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	XPS 14 9440	Intel BE201/BE200/AX211 Wi-Fi Controller Driver and Killer Intelligence Center Application	Version s prior to 36.25.3250	Version 36.25.3250 or later	10/15/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	XPS 14 9440	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/15/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	XPS 15 9500	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	10/22/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	XPS 15 9500	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Controller Driver	Version s prior to 36.25.3250	Version 36.25.3250 or later	10/22/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	XPS 15 9510	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/11/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	XPS 15 9510	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Controller Driver	Version s prior to 36.25.3250	Version 36.25.3250 or later	11/11/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	XPS 15 9520	Intel BE201/BE200/AX211 Wi-Fi Controller Driver and Killer Intelligence Center Application	Version s prior to 36.25.3250	Version 36.25.3250 or later	11/11/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	XPS 15 9520	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/11/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	XPS 15 9530	Intel BE201/BE200/AX211 Wi-Fi Controller Driver and Killer Intelligence Center Application	Version s prior to 36.25.3250	Version 36.25.3250 or later	11/10/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	XPS 15 9530	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/10/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	XPS 16 9640	Intel BE201/BE200/AX211 Wi-Fi Controller Driver and Killer Intelligence Center Application	Version s prior to 36.25.3250	Version 36.25.3250 or later	11/11/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	XPS 16 9640	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/11/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	XPS 17 9710	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/11/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	XPS 17 9710	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Controller Driver	Version s prior to 36.25.3250	Version 36.25.3250 or later	11/11/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	XPS 17 9720	Intel BE201/BE200/AX211 Wi-Fi Controller Driver and Killer Intelligence Center Application	Version s prior to 36.25.3250	Version 36.25.3250 or later	11/11/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	XPS 17 9720	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/11/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	XPS 17 9730	Intel BE201/BE200/AX211 Wi-Fi Controller Driver and Killer Intelligence Center Application	Version s prior to 36.25.3250	Version 36.25.3250 or later	11/11/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	XPS 17 9730	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/11/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	XPS 8940	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	09/08/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	XPS 8940	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3250	Version 36.25.3250 or later	10/15/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	XPS 8950	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	09/08/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	XPS 8950	Intel BE2xx/AX4xx/AX2xx/9xxx Wi-Fi Driver	Version s prior to 23.160.0.4	Version 23.160.0.4 or later	10/08/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	XPS 8950	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3250	Version 36.25.3250 or later	10/15/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	XPS 8960	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	09/08/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	XPS 8960	Intel Killer BE1750/AX1690/AX1675 /AX1650 Wi-Fi Driver	Version s prior to 36.25.3250	Version 36.25.3250 or later	10/15/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	XPS 9315 2-in-1	Intel BE201/BE200/AX211 Wi-Fi Controller Driver and Killer Intelligence Center Application	Version 36.25.3250 or prior to 36.25.3250	Version 36.25.3250 or later	11/11/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	XPS 9315 2-in-1	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version 23.160.0.9 or prior to 23.160.0.9	Version 23.160.0.9 or later	11/11/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
CVE-2025-24512, CVE-2025-30255, CVE-2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971	XPS 9320	Intel BE201/BE200/AX211 Wi-Fi Controller Driver and Killer Intelligence Center Application	Version s prior to 36.25.3250	Version 36.25.3250 or later	11/10/2025	Go to the Drivers & Downloads site for updates
CVE-2025-24512, CVE-2025-30255, CVE-	XPS 9320	Intel BE2xx/AX4xx/AX2xx/9xxx and Killer BE17xx/AX16xx Bluetooth Driver	Version s prior to 23.160.0.9	Version 23.160.0.9 or later	11/10/2025	Go to the Drivers & Downloads site

2025-33029, CVE-2025-35963, CVE-2025-35967, CVE-2025-35971						for updates
--	--	--	--	--	--	-----------------------------